

	Typ e	Hits	Search Text	DBs	Time Stamp	Comments	Error Definit ion
1	BRS	5031	resist with oxidation	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/07/09 11:10		
2	BRS	1095	resist adj oxidation	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/30 16:46		
3	BRS	766	resist adj oxidation	USPAT	2004/06/30 16:46		
4	BRS	28	photoresist adj oxidation	USPAT	2004/06/30 16:56		
5	BRS	47	photoresist adj oxidation	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/30 17:07		
6	BRS	0	oxidation with resisit with oxygen	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/30 17:08		

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition
7	BRS	0	resisit with oxidation with oxygen	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/3 0 17:08		
8	BRS	0	resisit with oxidation	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/3 0 17:08		
9	BRS	200	resist with oxidation with oxygen	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/07/0 7 11:55		
10	BRS	0	(high with temperatue with oxidation) same resist	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/07/0 1 10:46		
11	BRS	0	(high with temperatue with oxidation) and (resist or photoresist)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/07/0 1 10:47		

	Typ e	Hits	Search Text	DBs	Time Stamp	Comments	Error Definit ion
12	BRS	2	(high with temperature with oxidation)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/07/0 1 10:48		
13	BRS	7	(high with temperature) same oxidation	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/07/0 1 11:10		
14	BRS	0	((high with temperature) same oxidation) and (resist or photoresist)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/07/0 1 11:10		
15	BRS	5538	134/1.3,26.ccls. or 438/509,530,539,708,725,770,776,778,780,781.ccls.	USPAT; US-PGPUB	2004/07/0 7 11:57		
16	BRS	2364	(134/1.3,26.ccls. or 438/509,530,539,708,725,770,776,778,780,781.ccls.) and (resist or photoresist)	USPAT; US-PGPUB	2004/07/0 7 11:58		

	TYP e	Hits	Search Text	DBs	Time Stamp	Comments	Error Definit ion
17	BRS	816	((134/1.3,26.ccls. or 438/509,530,539,708,72 5,770,776,778,780,781. ccls.) and (resist or photoresist)) and oxidation	USPAT; US-PGPUB	2004/07/0 7 11:58		
18	BRS	594	((134/1.3,26.ccls. or 438/509,530,539,708,72 5,770,776,778,780,781. ccls.) and (resist or photoresist)) and oxidation) and oxygen	USPAT; US-PGPUB	2004/07/0 7 11:59		
19	BRS	424	((134/1.3,26.ccls. or 438/509,530,539,708,72 5,770,776,778,780,781. ccls.) and (resist or photoresist)) and oxidation) and oxygen and pressure and temperature	USPAT; US-PGPUB	2004/07/0 9 17:01		

	Typ e	Hits	Search Text	DBs	Time Stamp	Comment s	Error Definit ion
20	BRS	77	(((((134/1.3,26.ccls. or 438/509,530,539,708,72 5,770,776,778,780,781. ccls.) and (resist or photoresist)) and oxidation) and oxygen and pressure and temperature) and (resist with (oxidation or ash\$3))	USPAT; US-PGPUB	2004/07/0 9 12:38		
21	IS& R	1	("6410455").PN.	USPAT	2004/07/0 9 11:10		
22	IS& R	3	((("6043004") or ("6231775") or ("6599438")).PN.	USPAT	2004/07/0 9 16:44		
23	BRS	92	ashing and (pure near oxygen)	USPAT; US-PGPUB; EPO; IBM_TDB	2004/07/0 9 16:45		
24	BRS	48	(ashing and (pure near oxygen)) and (resist or photo)	USPAT; US-PGPUB; EPO; IBM_TDB	2004/07/0 9 16:45		
25	BRS	741	430/329.ccls.	USPAT; US-PGPUB	2004/07/0 9 17:02		
26	BRS	14	430/329.ccls. and (pure with oxygen)	USPAT; US-PGPUB	2004/07/0 9 17:02		